

INVENTOR(s): Richard Ganley, et al.; TITLE: "Wireleass Microphone Communication System" ATTY. DOCKET NO. 19036/41594/US; Page 1 of 7 Marshall, Gerstein & Borun LLP 312-474-6300 - Richard H. Anderson

Fig. 1




F i g. 2



INVENTOR(s): Richard Ganley, et al.;
TITLE: "Wireleass Microphone Communication System"
ATTY. DOCKET NO. 19036/41594/US; Page 2 of 7
Marshall, Gerstein & Borun LLP 312-474-6300 - Richard H. Anderson

Fig. 3



F i g. 4




Fig. 5

ALARM MESSAGE

BATTERY POWER OF MICROPHONE OF USER 1 IS **RUNNING SHORT**

OPERATOR A

OPERATOR B MUST REPLACE BATTERY OF MICROPHONE OF USER 1


OPERATOR B


BATTERY OF MICROPHONE OF USER 1 HAS BEEN REPLACED

69

INVENTOR(s): Richard Ganley, et al.;
TITLE: "Wireleass Microphone Communication System"
ATTY. DOCKET NO. 19036/41594/US; Page 4 of 7
Marshall, Gerstein & Borun LLP 312-474-6300 - Richard H. Anderson

F i g. 6





F i g. 7




Fig.8





Fig.9



INVENTOR(s): Richard Ganley, et al.; TITLE: "Wireleass Microphone Communication System" ATTY. DOCKET NO. 19036/41594/US; Page 6 of 7 Marshall, Gerstein & Borun LLP 312-474-6300 - Richard H. Anderson

Fig. 10




Fig. 11




Fig. 12

